Approved For Release 1999/09/17 : CIA-RDP78-03097A000800020054-5

Chief, RE & CD, O/L

17 March 1959

Chief, 25X1A8a

25X1A6a

25X1A6a

Window and Sash Installation in Housing on

- 1. Enclosed are single sets of specifications and drawings covering a window and sash replacement project has budgeted 25X1A8a for accomplishment late this summer with Fiscal Year 1960 funds. It is requested that your office review the plans and specifications and transmit your approval or comments to this office as soon as practicable. During your review, any questions regarding details may be discussed with the Chief of our 25X1A9a Engineering Staff, on Branch 2915.
- 2. The replacement of the existing wooden window frames and sash in the 16 GSWK built houses becomes necessary as a result of serious termite damage. This damage is so extensive that replacement is necessary as a matter of protection of life and property. During the 1957 typhoon season one of these houses had whole window frames blown in, with considerable resultant damage to furnishings and interior by wind and water. Considerable patching and painting was engaged in during 1958 to keep these housing units fit and safe. Adequate permanent repair cannot safely be delayed.
- 3. The enclosed plans and specifications conform to U.S. Army, District Engineer standards and cover the type of construction which the services have been employing in new and replacement construction in recent years. The plans and specifications may be retained for your files.

25X1A9a

#	 TOB	UI	むち	1	

l set plans

1 set specs

This document part of classified integrated file. NAME CHECK required prior to individual classification action.

WMK/jep

Distribution:

Orig & 1 - Addressee

1 - WMK

. - Chrono 🗸

1 - Exec

Approved For Release 1999/09/17 : CIA-RDP78-03097A000800020054-5

A second second

Class. Charge

Maxt Replace was wi-

Nate: 0/09 56

Approved For Release 1999/09/17 : CIA-RDP78-03097A000800020054-5

ORIGINAL DOCUMENT MISSING PAGE(S):

attochment